

❗ <b>ISSUE</b>	⚠ <b>MOST COMMON CAUSE</b>	🛡 <b>REMEDY</b>
<b>Will not enter set up</b>	➤ Pressing the wrong SW1 button	Verify that the SW1 button on I/O board is being pressed, ensure ribbon cable is fully seated.
<b>Red light goes solid on setup</b>	➤ Drive is set to Manual/Night Mode	Toggle between Manual and Automatic on ON/OFF/HOLD OPEN switch and try again. Turn on DIP 3, toggle between Night Mode and Automatic, Turn off DIP 3 and try again.
<b>Receiver not working</b>	➤ Receiver not wired properly	Terminate Common and -24V to 7/8/18/29, +24V to 9, and NO to 10/11
<b>Issues opening/closing door</b>	➤ Arm installed improperly/stack pressure/wind	Verify that arm is installed properly, set DIPs 1/2/8/9 as needed
<b>Door opens but will not close</b>	➤ Torpedo sensing before fully open/Set up is not done	Turn on DIP 7
<b>Door difficult to push open</b>	➤ Arm installed improperly/Closed door force is on	Verify that arm is installed properly/turn off DIP 1
<b>Stack Pressure/wind</b>	➤ Dip switches and preload not set/Need doorstop or windbreak	Adjust preload/set DIPs 1/8/9 as needed/install floor stop or wind break
<b>No changes take effect</b>	➤ Amber light is on/not pressing button to confirm changes	Verify that SW1 on logic board is being pressed and amber LED is extinguishing to confirm setting changes
<b>Will not setup/open manually</b>	➤ Wrong drive/arm configuration	Verify that operator is installed in correct configuration/correct arm is being used for application
<b>Torpedo not working</b>	➤ Torpedo not wired properly	Verify that Torpedo is terminated correctly, and corresponding jumper is removed

MCI -SW10-19-NOV232021-USA-A© COPYRIGHT 2021 - 2022 PORTALP USA, INC




**TUCKER SW 10/19**

## Most Common Issues



**Customer Service: (412) 823-2537**



**PORTALP**  
Automatic Doors & Building Access Control

PORTALP USA, Inc. Automatic Doors  
WWW.PORTALP.COM