

If you encounter an “Operation Timeout” Error when programming sensors or the ATOMS™ garage door openers to the HU-100 hub, the issue may be with radio frequency interference from the wireless router. It is recommended that you do not place the hub on top or beside the wireless router. Using a longer cable separate the hub from the wireless router 3’ to 4’ away to avoid interference.