

SX-HX

24 VAC HARNESS ADAPTERS

SERVICE NUMBER: 112447.0001-2 & 112449.0001 KIT

Part Included: Harness & lead assembly. 1 1phase & 1- 3phase, Wirenuts

Tools Required: 5/16" nutdriver/screwdriver


Approximate Time Required: 10 Minutes

WARNING

BE SURE ELECTRICAL POWER HAS BEEN DISCONNECTED FROM THE INPUT POWER LINES PRIOR TO REMOVING THE ELECTRICAL BOX COVER. AN APPROPRIATE LOCKOUT/TAGOUT PROCEDURE IS RECOMMENDED

1. REMOVE POWER FROM UNIT. USE PROPER LOCKOUT/TAGOUT PROCEDURES (REFERENCE OSHA STANDARD 1910.147)
2. OPEN ELECTRIC BOX COVER WITH SREWDRIWER OR 5/16" NUT DRIVER.
3. INSTALL HARNESS AS SHOWN BELOW DEPENDING ON THE PHASE OF OPERATOR.
4. USE WIRE NUTS PROVIDED TO ATTACH TO END DEVICE.
5. HARNESSES WILL ONLY PLUG INTO RESPECTIVE SOCKETS ONE WAY.

1 PHASE



3 PHASE

