



SINGLE-GANG, ANGLED MOUNTING BOX MOUNTING TEMPLATE & INSTALLATION INSTRUCTIONS

WITH ELECTRICAL BOX:
NO PRE-DRILLING REQUIRED.


1. Loosely mount the device to the mounting box using the Device mounting holes (▲).
2. Wire the device as instructed by the device's User's Guide.
3. Secure the device/box to the electrical box using the Electrical Box mounting holes (●).

Be sure to use the provided screws, observing screw length (short screw for top hole, long screw for bottom hole).

WITHOUT ELECTRICAL BOX:

1. Place mounting template in desired installation location.
2. Select mounting hardware (not provided) appropriate for the application and drill appropriate size pilot holes in the Solid Surface mounting hole locations (✗).
3. Align mounting box with pilot holes and secure using mounting hardware (not provided).
BEA, Inc. recommends using mounting hardware of at least 1.75" in length for mounting the top of the box, and at least 2.5" in length for mounting the bottom of the box.
4. Finish installation by securing the desired device to the mounting box using the Device mounting holes (▲).

Be sure to use the screws provided with the device.



Print settings must be set to "ACTUAL SIZE."

Verify dimensions after printing.

- ✗ Box mounting holes (solid surfaces)
- Box mounting holes (electrical boxes)
- ▲ Device mounting holes